



SR 7 Route Development Plan Phase 1 – Morton to Elbe


Data collected January 2000 through December 2004, MP 0.00 to 16.82














SR 7 Route Development Plan Phase 1 – Morton to Elbe

Data collected January 2000 through December 2004, MP 0.00 to 16.82









SR 7 Route Development Plan Phase 1 – Morton to Elbe

Data collected January 2000 through December 2004, MP 0.00 to 16.82




All Other Causes

All Other Causes		
Defective Equipment	4	
Improper Passing	1	
Improper Parking	1	
Improper Turn	2	
Fail to Signal	1	
Other	11	
Unknown	7	
No Violation	8	
Total	35	




All Other Causes

Defective Equipment	1
Improper Passing	1
Improper Parking	0
Improper Turn	0
Fail to Signal	0
Other	4
Unknown	3
No Violation	4
Total	13



All Other Causes

All Other Causes	
Defective Equipment	2
Improper Passing	1
Improper Parking	
Improper Turn	1
Fail to Signal	1
Other	1
Unknown	1
No Violation	1
Total	8



Summary of Fatal and Disabling Accidents:

Location	Injury	Collision Type	Roadway Surface	Lighting	Alcohol Related	Cited Cause
MP 0.82	Disabling	Bicyclist struck by vehicle	Dry	Dark - No street lights	No	None
MP 1.80	Disabling	Opposite direction - Strikes front end of other vehicle (not head on)	Dry	Daylight	Had been drinking - ability not impaired	Over centerline
MP 2.02	Fatal	Strikes earth bank or ledge	Wet	Daylight	No	Exceeding reasonable safe speed
MP 7.86	Disabling	Opposite direction - Sideswipe	Wet	Daylight	No	Over centerline
MP 9.70	Disabling	Single vehicle - Hit roadway ditch	Dry	Daylight	No	Apparently asleep
MP 12.63	Disabling	Single vehicle - Overturned	Dry	Daylight	No	Inattention